

## M1000 FIRST STEP

## **Application and Specifications**

## **Application**

Wash your marine vessel properly, prior to the polishing process. Use appropriate tools (polishing machine, pad etc.) compatible with M1000.

Wipe the polish residue with a lint-free microfiber cloth. Always remove excess polish and do not let dry. Do not use at high speed. It is suitable for rotary and orbital machines.

## **Specifications**

Packaging	1 kg
Application Temperature	5°C-30°C
Sanding Level	P1000
Cutting Level	Heavy
Gloss Rate	%40