

Application

Surfaces should be dry and free of any dust, stain, and other contamination. Product is applied via spraying with trigger or spreading with sponge till surface shines.

Specifications

Packaging	500 mL
Chemical Resistance	11>pH>1
Density @23°C	0.89 g/cm3
рН	5.5-6